

Edge of Arlington Saw & Tool, Inc.

124 South Collins

Arlington, TX 76010

Phone: 817-461-7171 • Fax: 817-795-6651

Toll Free: 888-461-7171

Email: info@eoasaw.com

Website: www.eoasaw.com



Whiteside Machine 3-Wing Composite Drills 3 7/8" OAL Carbide-Tipped Quick Change Shank

Thank you for shopping with us! Whiteside Machine 3-Wing Composite Drills 3 7/8" OAL Carbide-Tipped Quick Change Shank are designed for extended life in fiberglass and other composites. The 7/16" hex shank provides a no-slip grip when used with a standard three jaw chuck. This shank design also makes switching to a different size so simple when used with our Quick Change Chucks. Accurate centering is ensured by the replaceable 1/8" high speed steel center point. Bits perform equally well in handheld electric or pneumatic drills as well as boring machines and drill presses. Can be resharpened or re-tipped.



Item #	Manufacturer	Size	Wings	Recommended Rev/Min	Overall Length	Note	Price
8030500	Whiteside Machine	1/2 in	3-Wing	2,500-3,000	3 7/8 in	Replaceable Center Point is Part #8070125 -- Optional 1/8 in Machine Drill Center Point is Part #8061240.	\$100.04
8030562	Whiteside Machine	9/16 in	3-Wing	2,500-3,000	3 7/8 in	Replaceable Center Point is Part #8070125 -- Optional 1/8 in Machine Drill Center Point is Part #8061240.	\$100.04
8030625	Whiteside Machine	5/8 in	3-Wing	2,500-3,000	3 7/8 in	Replaceable Center Point is Part #8070125 -- Optional 1/8 in Machine Drill Center Point is Part #8061240.	\$100.04

8030687	Whiteside Machine	11/16 in	3-Wing	2,500-3,000	3 7/8 in	Replaceable Center Point is Part #8070125 -- Optional 1/8 in Machine Drill Center Point is Part #8061240.	\$100.04
8030750	Whiteside Machine	3/4 in	3-Wing	2,500-3,000	3 7/8 in	Replaceable Center Point is Part #8070125 -- Optional 1/8 in Machine Drill Center Point is Part #8061240.	\$100.04
8030812	Whiteside Machine	13/16 in	3-Wing	2,200-2,800	3 7/8 in	Replaceable Center Point is Part #8070125 -- Optional 1/8 in Machine Drill Center Point is Part #8061240.	\$100.04
8030875	Whiteside Machine	7/8 in	3-Wing	2,200-2,800	3 7/8 in	Replaceable Center Point is Part #8070125 -- Optional 1/8 in Machine Drill Center Point is Part #8061240.	\$100.04
8030937	Whiteside Machine	15/16 in	3-Wing	2,200-2,800	3 7/8 in	Replaceable Center Point is Part #8070125 -- Optional 1/8 in Machine Drill Center Point is Part #8061240.	\$100.04
8031000	Whiteside Machine	1 in	3-Wing	2,200-2,800	3 7/8 in	Replaceable Center Point is Part #8070125 -- Optional 1/8 in Machine Drill Center Point is Part #8061240.	\$100.04
8031062	Whiteside Machine	1 1/16 in	3-Wing	2,000-2,500	3 7/8 in	Replaceable Center Point is Part #8070125 -- Optional 1/8 in Machine Drill Center Point is Part #8061240.	\$109.57
8031125	Whiteside Machine	1 1/8 in	3-Wing	2,000-2,500	3 7/8 in	Replaceable Center Point is Part #8070125 -- Optional 1/8 in Machine Drill Center Point is Part #8061240.	\$114.34
8031250	Whiteside Machine	1 1/4 in	3-Wing	2,000-2,500	3 7/8 in	Replaceable Center Point is Part #8070125 -- Optional 1/8 in Machine Drill Center Point is Part #8061240.	\$126.25
8031312	Whiteside Machine	1 5/16 in	3-Wing	2,000-2,500	3 7/8 in	Replaceable Center Point is Part #8070125 -- Optional 1/8 in Machine Drill Center Point is Part #8061240.	\$133.39
8031375	Whiteside Machine	1 3/8 in	3-Wing	2,000-2,500	3 7/8 in	Replaceable Center Point is Part #8070125 -- Optional 1/8 in Machine Drill Center Point is Part #8061240.	\$133.39
8031437	Whiteside Machine	1 7/16 in	3-Wing	2,000-2,500	3 7/8 in	Replaceable Center Point is Part #8070125 -- Optional 1/8 in Machine Drill Center Point is Part #8061240.	\$142.92
8031500	Whiteside Machine	1 1/2 in	3-Wing	2,000-2,500	3 7/8 in	Replaceable Center Point is Part #8070125 -- Optional 1/8 in Machine Drill Center Point is Part #8061240.	\$148.88
8031625	Whiteside Machine	1 5/8 in	3-Wing	2,000-2,500	3 7/8 in	Replaceable Center Point is Part #8070125 -- Optional 1/8 in Machine Drill Center Point is Part #8061240.	\$152.45
8031750	Whiteside Machine	1 3/4 in	3-Wing	2,000-2,500	3 7/8 in	Replaceable Center Point is Part #8070125 -- Optional 1/8 in Machine Drill Center Point is Part #8061240.	\$154.83

8031875	Whiteside Machine	1 7/8 in	3-Wing	2,000-2,500	3 7/8 in	Replaceable Center Point is Part #8070125 -- Optional 1/8 in Machine Drill Center Point is Part #8061240.	\$166.74
8032000	Whiteside Machine	2 in	3-Wing	1,800-2,300	3 7/8 in	Replaceable Center Point is Part #8070125 -- Optional 1/8 in Machine Drill Center Point is Part #8061240.	\$185.80
8032125	Whiteside Machine	2 1/8 in	3-Wing	1,500-2,000	3 7/8 in	Replaceable Center Point is Part #8070125 -- Optional 1/8 in Machine Drill Center Point is Part #8061240.	\$197.71
8032250	Whiteside Machine	2 1/4 in	3-Wing	1,500-2,000	3 7/8 in	Replaceable Center Point is Part #8070125 -- Optional 1/8 in Machine Drill Center Point is Part #8061240.	\$214.39
8032500	Whiteside Machine	2 1/2 in	3-Wing	1,500-2,000	3 7/8 in	Replaceable Center Point is Part #8070125 -- Optional 1/8 in Machine Drill Center Point is Part #8061240.	\$226.29